


Las Cruces

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 029435 (b)
Lease No. J. L. Keel "B"
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 28, 1957

Well No. 25 is located 1900 ft. from N line and 516.8 ft. from E line of sec. 6
SW/4 Sec. 6 17S 31E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SINCLAIR OIL & GAS COMPANY - WELL NO. 25 * J. L. KEEL "B" FARM

10-3/4"	32.75#	600'	300 sks
7"	17 - 20#	3700'	200 sks

Propose to drill to 3700' to test Grayburg 3050'-3150' and San Andres dolomite 3550'-TD.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SINCLAIR OIL & GAS COMPANY

Address P. O. Box 1470

Midland, Texas

By R. L. Brown

Title Division Clerk, Prod. Dept.