NMOCD NINCE OFFICE COPY

Form Approved.

5-USGS-ARTESIA 1-R. J. STARRAK-TULSA

1-A.B. CARY-MIDLAND 1-FILE

Form 9-331 Dec. 1973

UNITED STATES	Budget Bureatt No. 42-R1424
DEPARTMENT OF THE INTERIOR	5. LEASE
GEOLOGICAL SURVEY	IC-029418 (b) 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WE (Do not use this form for proposals to drill or to deepen or plug back to reservoir, Use Form 9–331–C for such proposals.)	= 1
reservoir, Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other	Skelly Unit
2. NAME OF OPERATOR	9. WELL NO. 104
Getty Oil Company	
3. ADDRESS OF OPERATOR	Grayburg Jackson
P. O. Box 730, Hobbs, N4 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See	11. SEC., T., R., M., OR BLK. AND SURVEY OR
below.) AT SURFACE: Unit Letter E 1980' FNL & 66 AT TOP PROD. INTERVAL:	
AT TOTAL DEPTH:	14. API NO. :
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF REPORT, OR OTHER DATA	NOTICE, 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3904 DF
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT	
TEST WATER SHUT-OFF	(NOTE: Report results of partials completion or zone change on Form 4-330.) U.S. BEULUSIUM MEXICO ARTESIA, NEW MEXICO
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clincluding estimated date of starting any proposed work. I measured and true vertical depths for all markers and zone	If well is directionally drilled, give subsurface locations and
Riser on 10 3/4" OD and 7" OD cas	sing brought to surface.
Inspected by B. W. Weaver (NYOCC) on	
Inspected by Mike Williams (NMOCC) on	tan tan t V E.,
Inspected by James Brasfield (USGS) or	. MAY 2 1979
Tuesday by Dind Taras (UCCC)	*BDD - 4070

REPORT, OR OTHER DATA	1 3907	ONS (SHOW DF, F	-	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Repor chang	RECEI	1979 ompletion or zone NAL SURVEY EW MEXICO	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin	directionally drill dril	ed, give subsurfac	pertinent dates, e locations and	
Riser on 10 3/4" OD and 7" OD casing b	rought to su	rrace.		
Inspected by B. W. Weaver (NYOCC) on		•	RECEI	VE
Inspected by Mike Williams (NMOCC) on		•	· · · · · · · · · · · · · · · · · · ·	V E.
Inspected by James Brasfield (USGS) on		•	MAY 2	1979
Inspected by Bird Jones (USGS) on	PR 2-5 1979	•	O. C. (artesia, de	3. Fice
Subsurface Safety Valve: Manu, and Type	- · · ·	Set @	Ft.	
18. Thereby certify that the foregoing is true and correct signed D. R. Crockeff Title Area Sup	DtDATE	APR 2.5 19	79	
APPROVED EX APPROVAL, IF ANY		APR 3 0 1979		
'See Instructions on Revers	se Side			