



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 029418 (b)
Unit Las #3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
Perforate and Fracture	XX		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

B ~~Las Cruces~~ Hobbs, New Mexico December 18, 1962
Well No. 12 is located 1980 ft. from N line and 1980 ft. from W line of sec. 14
SE/4 NW/4 Sec. 14 17-S 31-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Grayburg Jackson Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3913 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Move in & rig up pulling unit.
2. Pull rods & tubing.
3. Set Baker Retrivable Bridge Plug at approximately 3715'.
4. Perforate from approximately 3512' to 3626'.
5. Fracture with approximately 20,000 gallons sand-oil.
6. Pull retrievable bridge plug.
7. Return well to production.

RECEIVED

DEC 24 1962

O. C. C.
ARTEBIA, OFFICERECEIVED
DEC 20 1962
U. S. GEOLOGICAL SURVEY
ARTEBIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shelly Oil CompanyAddress Box 38Hobbs, New Mexico(ORIGINAL)
(SIGNED) H. E. AabBy _____
Title Dist. Supt.