

DEPARTMENT OF THE INTERIOR (Other instruct on re-verse side)  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

Copy to > 1-

Budget Bureau No. 42-R19...

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner B

9. WELL NO.

26

10. FIELD AND POOL, OR WILDCAT

Fren Seven Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

20-17S-31E

12. COUNTY OR PARISH

Eddy

13. STATE  
N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

1650' FSL & 330' FWL (Unit letter L)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3615' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Plug & Abandon

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Rigged up 3/11/76, installed BOP & WIH w/2-3/8" OD EUE tbg OE to 1950'. Circulated hole w/heavy mud. Spotted 35 sx Cl H cmt (100' plug) 1850-1950'. POH w/tbg. Stretched 5 1/2" csg, free point indicated @ 776'. Ran jet cutter & cut 5 1/2" csg @ 706'. Pulled & recovered 706' of 5 1/2" OD csg. WIH w/tbg to 685' & spotted 75 sx Cl H cmt across 5 1/2" OD csg stub & 7" OD csg shoe (170' cmt plug 785-615'). Spotted 10 sx Cl H cmt @ surface, installed regulation dry hole marker. P&A eff 3/13/76. Cleaned & levelled location in accordance w/USGS & BLM specifications. Your office to be notified when location is ready for inspection.

RECEIVED  
MAR 26 1976  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 3/24/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side