

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NMOCC

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐  
well well other

2. NAME OF OPERATOR

Getty Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 730, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: Unit Letter C 330' FNL & 1650' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) Casing Connections

5. LEASE

LC-029420 (B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Skelly Unit

9. WELL NO.

5

10. FIELD OR WILDCAT NAME

Fren 7-Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21-17S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3760' DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

MAY 7 1979

O. C. C.  
ARTESIA, OFFICE

Riser on 8 5/8" OD and 7" OD casing brought to surface.

Inspected by B. W. Weaver (NMOCC) on

Inspected by Mike Williams (NMOCC) on

Inspected by James Brasfield (USGS) on

Inspected by Bird Jones (USGS) on

APR 27 1979

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

*D. R. Crockett*

TITLE Area Supt.

DATE

APR 30 1979

(This space for Federal or State office use)

APPROVED BY

*Joe J. Lara*

ACTING DISTRICT ENGINEER

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 4 1979

MAY 1 1979

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO