5-USGS-ARTESIA

1-A.B. CARY-MIDLAND

1-FILE

1-R. T STARRAK-TULSA

Form 9–231 Dec. 1973	NMOCC C	CPY.		et Bureau No. 42-R1424	
UNITE	D STATES	5. LEAS	5. LEASE LC-02419 (A)		
	OF THE INTERIOR	22.22.00			
GEOLOGIC	OGICAL SURVEY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)) }	7. UNIT AGREEMENT NAME		
		8. FAR	8. FARM OR LEASE NAME Skelly Unit		
1. oil gas otl	her	9. WEL			
		2			
			DORWILDCATI n 7 Rivers	NAME	
P. O. Box 730, Hobbs, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17		17 ARE	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22-17S-31E		
below.) AT SURFACE: Unit Lett AT TOP PROD. INTERVAL:	er C 660' FNL & 1980' F		JNTY OR PARISH		
AT TOTAL DEPTH:		14. API	NO.	Ţ ···	
16. CHECK APPROPRIATE BOX REPORT, OR OTHER DATA	TO INDICATE NATURE OF NOTI	15. ELE	VATIONS (SHOV	V DF, KDB, AND WD)	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Casing Connect:	ions	(NOTE:	Report results of m change on Form 9	nultiple completion or zone 330)	
including estimated date of measured and true vertical d	starting any proposed work. If wellepths for all markers and zones pe	rtinent to this v	y armea, give su vork.)*		
Riser on 8 5/8" OL	and <u>7" OD</u> casing	rioughe c	. Surface.	RECEIVE	
Inspected by B. W.	Weaver (N-OCC) on			. JUL 1 0 1979	
Inspected by Nike	Williams (NYOCC) on			. O. C. C.	
Inspected by James	Brasfield (USGS) on			ARTEBIA, OFFICE	
Inspected by Bird	Jones (USGS) on	APR 3 0	1979		
Subsurface Safety Valve, Manu, a	and Type			et @Ft.	
18. I hereby gertify that the fore			•	4070	
SIGNED D. R. Crock	TitleArea {	Supt	ATE MAY 4	1979	
APPROVED BY (Ong. Sed.)	(This space for Federal or S JOE G. ACTING DISTRI TITLE	et enginee	DATE	JUL 9 - 1979	

CEIVED

MAY 7 1979

*See Instructions on Reverse Side