Copy to S7

UNITED STATES Form 9-331 (May 1963) DEPARTMENT OF THE INTERIOR 1-FOREMAN

SUBMIT IN TRIPLICATE*

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL :	SURVEY
--------------	--------

ther	instructions	on	re-
rse sid	e)		

	GEOLOGICAL SURVEY	LC-023413 A
	SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	
1.	OIL GAS OTHER	7. UNIT AGREEMENT NAME SKELLY UNIT
2.	NAME OF OPERATOR GETTY OIL COMPANY RECEIVED	SKELLI UNII
٠.	P. O. BOX 730, HOBBS, NEW MEXICO 88240 MAY 1 5 1978	9. WELL NO.
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT GRAYBURG JACKSON
	660' FSL & 660' FWL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 22-17-31
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE

EDDY N.M.

SUBSECUENT REPORT OF:

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

3822 D.F.

MOTICE	OF INTENTION IV.		
			
TEST WATER SHUT-OFF	PULL OR ALTER CASING	 WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) Brought Cmt. Above	2 7-Rivers XX
(Other)		(Note: Report results of multipl Completion or Recompletion Repo	rt and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-3-78. Rigged up E & H Well Service Unit. POH w/138-3/4" rods and pump; pulled 117 Jts. (3512') of 2-3/8" OD Tubing.

McCullough ran Cement Bond Log 2600-600' and found Top of Cement behind 7" casing @ 1120'. O:K. No Bridges.

4-4-78. Ran 122 Jts. (3679') 2-3/8" tubing set @ 3679'; ran 2" X 1-1/2" X 12' pump and placed well back on production.

RECEIVED

MAY 1.1 1978

W. S. BEULUNION MENTO

MRESIA, NEW MENTO

ORIGINAL SIGNER BY				
18. I hereby certify that the foregoing is true and correct				
SIGNED	TITLE .	AREA SUPERINTENDENT	DATE _	MAY 9, 1978
Dale R. Crockett				
(This space for Federal of State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE -	ACTING DISTRICT ENGINEER	DATE _	MAY 1 2 1978