

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. <del>LC-029420-B</del> <b>LC-0294186b</b>	
2. NAME OF OPERATOR <b>GETTY OIL COMPANY</b>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----	
3. ADDRESS OF OPERATOR <b>P. O. BOX 730, HOBBS, NEW MEXICO 88240</b>		7. UNIT AGREEMENT NAME <b>SKELLY UNIT</b>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <b>1278/5 660/W</b> <b>330' FSL &amp; 660' FEL</b>		8. FARM OR LEASE NAME <b>SKELLY UNIT</b>	
14. PERMIT NO.		9. WELL NO. <b>78</b>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>3849' D.P. 3859</b>		10. FIELD AND POOL, OR WILDCAT <b>GRAYBURG JACKSON (S.P. &amp; S.A.)</b>	
		11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA <b>23</b> <b>21-17-31</b>	
		12. COUNTY OR PARISH <b>EDDY</b>	
		13. STATE <b>N.M.</b>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <b>Brought cmt. above 7-Rivers</b> <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- Moved in and rigged up E & H Well Service 3-22-78. Pulled rods and tubing.
- Dresser Atlas ran Cement Bond Log 2500-1000' and found Top of Cement @ 2000'. Perforated 2 holes @ 1990'.
- Set packer @ 1811'; B.J. spotted 250 gals. 15% NE Acid 1998-1850'; cemented w/200 sxs. 50/50 Poz Mix, 4% Gel, 6# Salt/sk. and 100 sxs. Class "C" Cement w/2% CaCl and displaced cement to 1920'.
- 3-24-78. Bennett Wireline Company ran Temperature Survey and found Top of Cement @ 1400'. WOC.
- Drilled Cement 3-27-78 to 2010' and tested perforations @ 1990' w/500#. O.K.
- Ran 123 Jts. (3798') of 2-3/8" tubing set @ 3796'; SN @ 3760'; ran 2" X 1-1/2" X 16' Pump set @ 3760'; and placed well back on production 3-28-78.

RECEIVED  
MAY 11 1978  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED **DALE R. CROCKETT** TITLE **AREA SUPERINTENDENT** DATE **MAY 9, 1978**

(This space for Federal or State office use)

APPROVED BY **Joe A. Lara** TITLE **ACTING DISTRICT ENGINEER** DATE **MAY 15 1978**

CONDITIONS OF APPROVAL, IF ANY: