

ARTESIA OFFICE COPY

Budget Bureau No. 42-R353.
Approval expires 11-30-46.

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

UNITED STATES

Lease No. 029418 B

DEPARTMENT OF THE INTERIOR

Unit La "B"

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico - July 14, 1947

Well No. 3 is located 1980 ft. from N line and 1080 ft. from E line of sec. 23

CHK/4 SE/4 Sec. 23 17S 31E New Mexico
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)


Grapburg-Jackson Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ? ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After allowing cement to set 48 hours, drilled plug and tested casing shut-off OK in 7" OD casing set and cemented at 3202' with 150 sacks cement - Halliburton Process. Now drilling ahead.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY

Address Drawer D

Hobbs, New Mexico

By [Signature]

Title District Superintendent