5-USGS-ARTESIA STARRAK-TULSA 1-R. :

1-A.B. CARY-MIDLAND

Form 9-331 Dec. 1973

UNITED STATES

1-FILE Form Approved. Budget Bureau No. 42-R1424 LIMOCG CORY 5. LEASE C-020/18 (b)

DEPARTMENT OF THE INTERIOR [LC-029418 (D)
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	Skelly Unit
1. oil gas well other	9. WELL NO.
2. NAME OF OPERATOR	72
Getty Oil Company	10. FIELD OR WILDCAT NAME Grayburg Jackson
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
P. O. Box 730, Hobbs, M1 88240	AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 23-17S-31E
below.) AT SURFACE: Unit Letter K 1980' FSL & 1980' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Eddy New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3873' DF
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	RECEIVED
TEST WATER SHUT-OFF	JUL 1 0 1979 (NOTE: Report results of multiple completion or zone change on Form 9-330 . C. C. ARTESIA, OFFICE
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stational including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Riser on 8 5/8" OD and 4 1/2" OD casing by	
	term or Arra
Inspected by B. W. Weaver (NMOCC) on	. MAY 81 10.0
Inspected by Mike Williams (NYOCC) on	U.S. CHOLOGICAL CHOICE
Inspected by James Brasfield (USGS) on	ARTESIA, NEW III
Inspected by Bird Jones (USGS) on	MAY 1 1575 .
indpeace. of	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED SIGNED TITLE Area Sup	t. DATE
(This space for Federal or State	office use) SMOINEER HILL 9 - 1074
APPROVED BY BY APPROVAL IF ANY:	EMPINEER JUL 9 - 107-1