

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Las Cruces
Land Office
025702
Lease No.
Unit Mary D. Smith

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mexico,
February 21, 1947

Well No. 1 is located 495 ft. from [N] line and 425 ft. from [E] line of sec. 6


Lot 3, Sec. 6 17 S. 27 E. R.R.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South High Lonesome Artesia New Mexico.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show also, weights and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plan to plug back as follows: 1. 2 1/2" casing to 3560' with gravel and run 5 sack cement plug at 3560'. 2. 2 1/2" casing to 3560' with mud to approximately 2375' and then plug back at 2375'.



4-2-47
Asked M.Y. Jr. to file
Sub. Report on work covered by this notice.
m.h.s.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MARY D. SMITH, et al.

Address Box 597,

Artesia, N. Mex.

By

Date

for Lessee.