

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN  
(Other Instr.  
verse side)PLICATE  
as on re-Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 028731 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dodd

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Grayburg Penn

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

22-17-29

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER Plug and Abandon

2. NAME OF OPERATOR

Moran Oil Producing &amp; Drilling Corp. ✓

3. ADDRESS OF OPERATOR

P. O. Box 1919, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface1980/S 1880/E Section 22, T17S, R29E, Eddy County,  
New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3551 GL

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

XX

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On May 25, 1971, 8 5/8 casing was shot and pulled at 1223'  
Cement plugs were spotted:

50 sx at 1160-1270

25 sx at 225- 275

10 sx at surface

9# mud spotted between all cement plugs.

A 4" x 4' marker was installed. The location was cleared up and  
restored to the original contour. Location now ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 7-30-71

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

APPROVED

OCT - 1 1971  
H. L. BECKMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side

RECEIVED

AUG-21971

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO