

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate*
(Other instruct. on re-
verse side)

copy to SF
Form approved.
Budget Bureau No. 42-R1424.

1-ENGR

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME SKELLY UNIT	
2. NAME OF OPERATOR GETTY OIL COMPANY		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR P. O. BOX 730, HOBBS, NEW MEXICO 88240		9. WELL NO. 122	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1880' FEL and 660' FSL		10. FIELD AND POOL, OR WILDCAT FREN-7 RIVERS	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3820' GR	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 22, T-17-S, R-31-E	
		12. COUNTY OR PARISH EDDY	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 4:00 P.M. 10-13-77. Drilled 11" hole to 632'. Set 8-5/8" 24# J-55 casing at 632'. Cemented with 150 sacks 50-50 Poz-Mix C containing 6# salt/Sx. and 4% Gel and 1/4# Cello Flakes per sack and 150 sacks Class "C" w/2% CaCl₂. Cement Circulated. WOC 12 hours. Tested with 1000# for 30 minutes with no drop in pressure.

RECEIVED
OCT 31 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed By
Dale R. Crockett

TITLE AREA SUPERINTENDENT

DATE 10-26-77

(This space for Federal or State office use)

APPROVED BY Lee S. Lara
CONDITIONS OF APPROVAL, IF ANY:

TITLE ACTING DISTRICT ENGINEER

DATE NOV 10 1977

*See Instructions on Reverse Side