

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

MOCC COPY IN TRI DATE*
(Other instructions on reverse side)

copy to SF
Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-029419A	
2. NAME OF OPERATOR Getty Oil Company ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----	
3. ADDRESS OF OPERATOR P.O. Box 730 Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME -----	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 560' FSL & 660' FWL, Sec. 22		8. FARM OR LEASE NAME Skelly Unit	
14. PERMIT NO.		9. WELL NO. 123	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3812 GR		10. FIELD AND POOL, OR WILDCAT Fren 7-Rivers	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 22-17S-31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 10:00 AM 9-7-77. Drilled 12 1/4" hole to 637' - Set 8 5/8" 24# K-55 casing at 636'. Cemented with 250 sacks Class-C. Cement circulated - WOC 18 hours. Tested 8 5/8" with 800# for 30 minutes, no drop in pressure

RECEIVED
SEP 30 1977
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

David C. Carter

TITLE

Area Superintendent

DATE

9-28-77

(This space for Federal or State office use)

APPROVED BY

John D. Lutz

TITLE

ACTING DISTRICT ENGINEER

DATE

OCT 3 - 1977

CONDITIONS OF APPROVAL, IF ANY: