

UNITED STATES NM 88210  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐  
well well

2. NAME OF OPERATOR

Getty Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 728 Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

2560' FSL & 2630' FEL  
AT SURFACE: (Unit Letter J)  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) COMMENCE DRILLING OPERATIONS

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

SPUD 12 1/4" HOLE, 7:30 PM, 12-18-84  
TOTAL DEPTH 511'

1. Ran 497' (12 JTS) 8 5/8" OD 28# K-55 Csg & Set @ 511'.
2. Cemented W/400 sx. Class H Cement containing 1/4# Flocele, & 2% CACL. Cement circulated. Job complete 6:00 AM, 12-19-84, WOC 18 Hrs.
3. Tested 8 5/8" Csg to 1000# for 30 minutes, 12:01-12:31 AM, 12-20-84. Tested OK. Job complete 12:31 AM, 12-20-84.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED W. H. Baker TITLE Dist. Opr's. Mgr. DATE 1-15-85

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

FEB 1 1985

\*See Instructions on Reverse Side

NEW MEXICO