

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Submittal (Other instruct on reverse side)

copy 0-1
Form No. 1-61

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER RECEIVED

2. NAME OF OPERATOR Atlantic Richfield Company ✓ OCT 10 1973

3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface ARTESIA, OFFICE

1980' FSL & 660' FEL (Unit Letter I)

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3636' GR

5. LEASE DESIGNATION AND SERIAL NO. LC029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME Turner "B" (A)

9. WELL NO. 53

10. FIELD AND POOL, OR WILDCAT Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30, T17S, R31E

12. COUNTY OR PARISH 18. STATE Eddy N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF PULL OR ALTER CASING
FRACTURE TREAT MULTIPLE COMPLETE
SHOOT OR ACIDIZE ABANDON*
REPAIR WELL CHANGE PLANS
(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF REPAIRING WELL
FRACTURE TREATMENT ALTERING CASING
SHOOTING OR ACIDIZING ABANDONMENT*
(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to fracture treat this well starting about 10/15/73 as outlined below:

POH w/rods & tubing.
Fracture perforations 3356' to 3397' w/10,000 gal slick fresh water containing 14,000# 20/40 sand in two stages separated w/300# benzoic acid flakes.
Swab until sand influx stops.
Return well to production.

Present production is 15 BOPD & 33 BWPD.

RECEIVED
OCT 13 1973
GEOLOGICAL SURVEY
MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED C.D. Sitches TITLE District Drlg. Supv. DATE 10/01/73

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
OCT 9 1973
H. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side