

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

N. M. O. C. C.
 SUBMIT IN TR. (Other instructi
 verse side)

Form approved.
 Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
 Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

AUG - 1 1978

5. LEASE DESIGNATION AND SERIAL NO.
 LC-029418-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
 Skelly Unit

8. FARM OR LEASE NAME

9. WELL NO.
 138

10. FIELD AND POOL, OR WILDCAT
 Fren 7-Rivers

11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA
 SEC. 26, T-17-S, R-31-E

12. COUNTY OR PARISH
 Eddy

13. STATE
 New Mexico

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
 GETTY OIL COMPANY

3. ADDRESS OF OPERATOR
 P. O. BOX 730, HOBBS, NEW MEXICO 88240 O. C. C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
 At surface
 UNIT LETTER C, 510' FNL, AND 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
 3844 GR

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

La Rue Drilling Co. spudded 11" hole at 2:00 p.m. on 6-19-78. Drilled 11" hole to 695'. Set 8 5/8" 23# casing at 695', and B.J. cemented with 150 sxs. 50/50 Poz, 4% Gel, 10# Salt, 1/4# Cello Flakes/sk. and 125 sxs. Class "C" with 2% CaCl. 10 sxs. cement circulated. Tested casing with 1000# for 30 min. with no drop in pressure.

RECEIVED

JUL 31 1978

U. S. GEOLOGICAL SURVEY
 ARTESIA, NEW MEX.

ORIGINAL SIGNED BY

18. I hereby certify that the foregoing is true and correct

SIGNED Dale R. Crockett TITLE AREA SUPERINTENDENT DATE 7-26-78

(This space for Federal or State office use)

APPROVED BY Joe J. Lara TITLE ACTING DISTRICT ENGINEER DATE JUL 31 1978

CONDITIONS OF APPROVAL, IF ANY: