

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87508
OCT 17 1983
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
648

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- **Injector**

2. Name of Operator
DEPCO, Inc.

3. Address of Operator
800 Central, Odessa, TX 79761

4. Location of Well
UNIT LETTER **0** **1117** FEET FROM THE **South** LINE AND **1461** FEET FROM
THE **East** LINE, SECTION **10** TOWNSHIP **19-S** RANGE **28-E** NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
State 648 Ac. 811

9. Well No.
69

10. Field and Pool, or Wildcat
Artesia, Q,G, SA

12. County
Eddy



15. Elevation (Show whether DF, RT, GR, etc.)
3506 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-23-83: Set CIBP at 1975'.

9-28-83: Spotted 15 sxs cement plug on top of CIBP. Loaded hole to 680' w/9# mud laden fluid. Spotted 35 sxs cement plug. Pulled tbg. and pumped 75 sxs cement. Did not circulate.

9-29-83: Pumped 100 sxs cement. No returns. Pumped 60 sxs cement with good returns. Left 4 1/2" & 7" csg. full of cement.

Installed dry hole marker and cleaned location.

Mr. Mike Williams with the Oil Commission witnessed the plugging procedure.

*Post ID-2
10-21-83
P+H*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leon Standard TITLE Field Engineer DATE 10-14-83

APPROVED BY Randy Brooks TITLE Geologist DATE 2-13-84

CONDITIONS OF APPROVAL, IF ANY: