

COMPANY <i>Mesa Oil Co</i>		PROPERTY NAME <i>A. Dooley</i>	WELL NO. <i>1</i>
DATE	LOCATION ULSTR) <i>D 4-19-28</i>	FOOTAGE	
API NO.		POOL	

- ① RIH w/ collar locator + find perforations
- ② Spot 40 5x e perts + tag
- ③ Spot 30 5x or 100' plug e GB 2054'
- ④ Spot 30 5x or 100' plug e Qu 1690'
- ⑤ Perforate e 716' + sg. 30 5x outside of pipe leaving 100' inside TAG
- ⑥ Perforate e 285' + attempt to circulate cement to surface on backside leaving pipe full.
- ⑦ Clean + level location + set P+H marker
- ⑧ Place mud between pluggs
- ⑨ Contractor is responsible for location + roads.

Before

10" e
235'

8 1/4 e
676

CASING RECORD:

10" e 235'

8 1/4 e 676

There is no record of production lsg.

There is no record of cementing.

Records show a plug e 2871'

Formation tops

San Andres e 2490'

GB e 2054'

Qu e 1690'

BX e 610'

TX e 368'

2871'

