

YATES PETROLEUM CORPORATION
Ottawa AOW Federal #3
Section 10-T19S-R25E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7710-7755' (Canyon): TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY:
3' of oil and 1350' of water. SAMPLER: 1.00 cfg, 100 cc oil and 1800 cc water.
PRESSURES: IHP 3756; IFP 140-286; ISIP 2422; FFP 262-576; FSIP 2427; FHP 3722

DST #2 7761-7797' (Canyon): TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY:
950' of water. SAMPLER: .37 cfg and 2250 cc water. PRESSURES: IHP 3775;
IFP 170-235; ISIP 2205; FFP 280-375; FSIP 2425; FHP 3778

DST #3 7804-7845' (Canyon): TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY:
471' of oil, 568' of water and 409' of rathole mud. SAMPLER: 2.56 cfg, 1050 cc
of oil and 400 cc water. PRESSURES: IHP 3782; IFP 311-344; ISIP 2346; 2nd FP
311-631; 2nd SIP 2346; FHP 3782