



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office N M  
Lease No. 01119  
Unit A

RECEIVED

OCT 1 1962

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 29, 19 58

Welch, Et AL  
Well No. 7 is located 330 ft. from N line and 990 ft. from E line of sec. 5

Lot 1, Sec. 5      21S      27E      N. M. P. M.  
(1/4 Sec. and Sec. No.)      (Twp.)      (Range)      (Meridian)

Cedar Hill      Eddy      New Mexico  
(Field)      (County or Subdivision)      (State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per phone conversation 7-29-58, we plugged the above well as follows:

Filled hole to bottom of 7 in. and cemented with 10 sacks. Knocked off 7 in. at top of cement and pulled 410 ft. of 7 in. cemented stub with 10 sacks.

Pulled 8 inch casing, filled hole to surface and set regulation marker.

COPY

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company V. S. Welch

Address Box 1417

Artesia, New Mexico

By /s/ V. S. Welch

Title Owner