	IN. M. Q. C.	C. 1	Capy to SI
Form 9-331 (May 1963)	UN ED STATES RTMENT OF THE INTER	SUBMIT IN TRIE	Form approved.
GEOLOGICAL SURVEY			01165
SUNDRY N (Do not use this form for p	OTICES AND REPORTS roposals to drill or to deepen or plug PLICATION FOR PERMIT—" for such	ON WELLS back to a different reservoir. proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OH. 571 CAS [7]	:		7. UNIT AGREEMENT NAME
WELL WELL OTHI	čr	RECEIVED	8. FARM OR LEASE NAME
Yates Petroleum Corporation / 2 1074			Williamson "BC"
3. ADDRESS OF OPERATOR		DEC 2 1374	9. WELL NO.
207 South 4th Str	eet-Artesia, NM 88 clon clearly and in accordance with an	8210 ny State requisements.	10. FIELD AND FOOL, OR WILDCAT
See also space 17 below.) At surface	L & 660' FEL of Sec	ARTESIA. OFFICE	Burton Delaware 11. sec., T., B., M., OR BLE. AND SURVEY OR AREA Sec. 7-20S-29E
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	Unit P 12. COUNTY OR PARISH 13. STATE
	3262'		Eddy NM
16. Check	Appropriate Box To Indicate	Nature of Notice, Report, or	
NOTICE OF	INTENTION TO:	SUBSEC	QUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING Shut in	Status V
REPAIR WELL (Other)	CHANGE PLANS	(Note: Report result	ts of multiple completion on Well pletion Report and Log form.)
proposed work. If well is d nent to this work.)* Well shut in - Ap	proved for disposal to plug and abando	l well on this lea	s, including estimated date of starting an cal depths for all markers and zones pertions. se, held for
		•	
	•		
	•	•	•
			RECEIVED
			NOV 1 1 1974
	·	-	U.S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO
18. I hereby ceptify/that the forego	oing is true and correct	Engineer	