

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved by
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Drilling		7. UNIT AGREEMENT NAME NONE	
2. NAME OF OPERATOR INEXCO OIL CO. ✓		8. FARM OR LEASE NAME ARCO FED. COM.	
3. ADDRESS OF OPERATOR 1301 Americana Bldg., Houston, Texas 77002		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1200 FNL, 1200 FWL		10. FIELD AND POOL, OR WILDCAT CATCLAW DRAW	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T21S, R26E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) To be determined at later date		12. COUNTY OR PARISH Eddy	
		13. STATE N. Mex.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other) Cementing 13-3/8" Csg.	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 1) Spud 11:00 P.M. (MDT) 8-3-73
- 2) Drilled 17 1/4" hole to 555 ft. Lost 100% Returns at 154 ft.
- 3) Cemented 13-3/8", 48#/ft, H-40 Casing at 555 ft. w/375 sx. Trinity Lite Water +3# Gilsonite' sx. + 1/4# Flosele/sx., followed by 150 sx Class "C" + 2% CaCl2. No Mud or Cement returns to surface. Ran 1" tbg. to 193 ft. and cemented annulus to surface w/300 sx. Trinity Lite Water Neat. WOC 8 hrs.
- 4) Installed Bradenhead & BOPE
- 5) Satisfactorily pressure tested casing & BOPE to 600 psig for 1/2 hr., no pressure loss noted. Continued drilling operations in 12 1/4" hole.

RECEIVED

AUG 20 1973

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Delven Mermis
(This space for Federal or State office use)

TITLE Div. Prod. Mgr.

DATE 8/13/73

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

APPROVED
AUG 22 1973
K. L. BEEKMAN
ACTING DISTRICT ENGINEER