

HILLIN PRODUCTION COMPANY

D.S.T. REPORTS

09-10-73

WELL: JCW State #2

TEST NUMBER: #4

DEPTH: 11,410'

TOTAL FOOTAGE TESTED: 10,420 - to 10,610 - S.P. test.

Bottom Pkrs. failed

Min. Pre-flow

Final Flow Pressure

Min. I.S.I.P.

Min. Flow

Final Flow Pressure

Min. F.S.I.P.

Min. 2nd. Flow

Final Flow Pressure

Min. 2nd. S.I.P.

Hydrostatic IN:

Hydrostatic OUT:

Temperature:

REMARKS: Tool Open: *W/weak blow - no pressure due to pkrs. failure*

Gas to surface: Mud to surface:

Oil to surface: Gravity:

FLOW:

FLOW:

FLOW:

FLOW:

RECOVERED:

SAMPLE CHAMBER:

Tool open with weak blow. Gas to surface in 27 minutes - too small to measure.
Mis-run due to packer failure of bottom packers.