

Details of bop test


Hanagan Petroleum Corporation

Ocotilla Hills #1


Contractor: Moran Drlg. Rig 8

Test by Yellow Jacket Tools and Services, Inc.

=====Transposition of the pressure recorder charts=====



=====Transposition of the pressure recorder charts=====



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Carlsbad Area, Roswell District, New Mexico. Test was made with test plug landed in casing head with the following test results:

Arrived location - rig drilling.