🔊 · *

LIVINGSTON RIDGE UNIT # 1 SECTION 36, T21S, R30E Eddy County, New Mexico

August 23, 1974 Rigged down, Move larger Rig and Rigged up. August 29, 1974 Finished rigging up and hauled water. August 30, 1974 Drilling from 63' to 66' in red clay. Drilling from 66' to 71 in red clay. August 31, 1974 September 1, 1974 Drilling from 71' to 78' in red clay. September 2, 1974 Drilling from 78' to 85' in red clay. Worked 8 hrs. September 3, 1974 Drilling from 85' to 91' in red clay. Worked 9 hrs. September L, 1974 Drilling from 91' to 100' in red clay. 11 11 September 5, 1974 Drilling from 100' to 105' in red clay. Worked 8 hrs. September 5, 1974 Hung Bailer in hole. Cleaning out cavings. Worked 9 hrs. Drilling from 105' to 112' in white shells. Worked 8 hrs. September 7, 1974 tember-8, 1974 Off September 9, 1974 Drilling from 112' to 120' in red clay & shells. Worked 8 hrs. September 10, 1974 Drilling from 120' to 130' in red clay. 11 11 September 11, 1971: Drilling from 130' to 138' in red clay. П 11 September 12, 1974 Drilling from 138' to 146 in red clay. Worked 9 hrs. September 13, 1974 Drilling from 146 to 160' in red clay. Worked 12 hrs. September 14, 1974 Drilling from 160 to 165' in red clay & shells. Worked 8 hrs. September 15, 1974 Off September 16, 1974 Drilling from 165' to 178' in red clay & shells. Worked 9 hrs. Hauled water. September 17, 1974 Drilling from 178' to 185' in red clay & shalls: Worked 8 hrs. September 13, 197), Drilling from 1851 to 1891 in red clay. Vorted A hrs. Rained out and busted magneto cap. September 19, 1974 Drilling from 1891 to 1951 in red clay 4 shells. Worked 8 hrs. } Repair on rig motor 3 hrs.

September 20, 1971. Drilling from 195' to 205' in red clay & shells.

ļ

.