

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87508

WELL API NO.
30-015-26760

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG 9280

7. Lease Name or Unit Agreement Name

Mary AIV State

8. Well No.
5

9. Pool name or Wildcat
Lost Tank Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter A : 660 Feet From The North Line and 330 Feet From The East Line
Section 36 Township 21S Range 31E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3643' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: Set Surface and Intermediate Casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 26" hole 9:50 AM 12-13-91. Set 40' of 20" conductor and ready-mix to surface. Notified NMOCD, Artesia, NM, of spud. Resumed drilling 17½" hole 2:00 PM 12-19-91. Ran 19 joints 13-3/8" 54.5# J-55 casing set 850'. Guide shoe set 850', insert float set 805'. Cemented with 600 sx PSL "C" + 2% CaCl2 + 1/4#/sx Celloseal (yield 1.76, wt 12.9). Tailed in w/250 sx Class "C" + 2% CaCl2 + 1/4#/sx Celloseal (yield 1.32, wt 14.8). PD 6:25 PM 12-20-91. Bumped plug to 1000 psi, released pressure, held OK. Circulated 270 sacks. WOC. Drilled out 9:00 PM 12-21-91. WOC 26 hrs and 35 mins. NU and tested to 500 psi for 15 mins, OK. Reduced hole to 11" and resumed drilling. TD 11" hole 12-27-91. Ran 103 joints 8-5/8" 32# HC-80 and J-55 casing set 4260'. Float shoe set 4260', float collar set 4128'. Cmt'd w/1400 sx PSL "C" + 5#/sx Gilsonite + 1/4#/sx Celloseal + 10#/sx Salt (yield 1.94, wt 12.7). Tailed in w/200 sx "C" + 5#/sx Gilsonite + 1/4#/sx Celloseal + 2% CaCl2 (yield 1.32, wt 14.8). PD 6:10 PM 12-28-91. Bumped plug to 2100 psi, float held OK. Circulated 237 sacks. WOC. Drilled out 6:10 PM 12-28-91. WOC 24 hrs. NU and tested to 1000 psi for 15 mins, OK. Reduced hole to 7-7/8". Resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 1-6-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY

WILLIAMS

SUPERVISOR DISTRICT I

APPROVED BY _____ TITLE _____ DATE JAN 8 1992

CONDITIONS OF APPROVAL, IF ANY: