

FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 73678 Location: Lindrith Unit No. 49 Operator #: 2999 Operator Name: MDT P/L District: Ditto Coordinates: Letter: G Section 9 Township: 24 Range: 3 Or Latitude Longitude Pit Type: Dehydrator Location Drip: \(\) Line Drip: Other: Site Assessment Date: \(/ 14 / 94 \) Area: \(\) Run: 83
SITE ASSESSMENT	NMOCD Zone: (From NMOCD Maps) Inside Outside Outside (I) Fee (3) Outside Outside (I) Fee (3) Indian Depth to Groundwater Less Than 50 Feet (20 points) Forester Than 100 Ft (0 points) Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; ls it less than 200 ft from a private domestic water source? Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (10 points) (2) Greater Than 1000 Ft (10 points) (3) Name of Surface Water Body StareDur Carjen (Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream (1) < 100'(Navajo Pits Only) (2) > 100' TOTAL HAZARD RANKING SCORE: Depuis State (2) (1) State (2) (1) Fee (3) State (2) (1) Fee (3) State (2) (2) (3) Noticinal Distance of Companies (2) (1) (2) > 100' TOTAL HAZARD RANKING SCORE: Depuis State (2) (1) (2) > 100' TOTAL POINTS
\mathbf{S}	
МА	Remarks: Redline Book - Duride Vunterable Zone Topo - Ouride I pit. Willclose Pitary. Site was not on Topo. Location was opproximated
REMA	
	PUSHIN

	ORIGINAL PIT LOCATION
	Original Pit: a) Degrees from North 334° Footage from Wellhead 112′ b) Length: 13′ Width: 12′ Depth: 2′
N.	
ORIGINAL PIT LOCATION	Not properly 324,
	Remarks:
	Remarks: _ Pictures (0 1429 (1-4) roll!
KS	Pictures @ 1429 (1-4) roll
EMARKS	Pictures @ 1429 (1-4) roll
REMA	Pictures @ 1429 (1-4) roll
REMARKS	Pictures @ 1429 (1-4) roll
REMA	Pictures (0 1429 (1-4) roll) Dump Truck
REMA	Pictures @ 1429 (1-4) roll