5-USGS-Artesia 🗸 1-Pogo, Midland N.M.O.C.D. C( Y 1-W.A. Frnka '-Pogo, Houston Form 9-331 ]-R. Blohm-Midland 1-JDM, Engr Form Approved. Budget Bureau No. 42-R1424 UNITED STATES 1-File 5. LEASE DEPARTMENT OF THE INTERIOR NM-25876 6. IF INDIAN, ALLOTTEE OR TRIBE NAME GEOLOGICAL SURVEY 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 8. FARM OR LEASE NAME Getty Federal 🌌 1. oil gas XXXX well well other 9. WELL NÖ. 🤼 🤼 2. NAME OF OPERATOR GETTY OIL COMPANY, 10. FIELD OR WILDCAT NAME 3. ADDRESS OF OPERATOR Wildcat - Beta Prospect PO BOX 730, HOBBS, NM 88240 11. SEC., T., R., M., OR BLK. AND SURVEY OR 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.) Sec. 24, T22S, R31E Unit Ltr. G. 1980' FNL & 1980' AT SURFACE: 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: Eddy New Mexico AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3574.2 GL REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL E: Report results of multiple completion or zone NOV 1 4 1980 change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES M.S. GEOLUGICAL SURVEY ARTESIA, NEW METTERS ABANDON\* Run Hner (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* 10/29/80 Drilled 6 1/8" hole to 14,935'. Ran 69 jts. (2938!) 5" OD 18# N-80Hydrill R-3 Casing w/MWL Float equipment and liner hanger. Liner set from 14,934' to 11,964' (283'). Howco cemented 5" Tiner w/100 sxs. POZ H w/2% Gel, .75% CFR-2, .4% H-22A. Tailed in w/300 sxs Class H .6% H-22A, .5% CFR-2, 5#/sx KCL, 2% Lime and 25 bbls. Sam 4 Spacer. Bumped plug at 3:30 P.M. WOC. 10/31/80 Tested 5" casing to 1200# for 30 min. OK. Subsurface Safety Valve: Manu. and Type \_\_\_ Set @ 18. I hereby certify that the foregoing is true and correct Area Supt.

ACCEPTED FOR RECORD Spa PETER W. CHESTER CONDITIONS OF PPROVAL, IF ANY 7 1980 U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO See Instructions on Reverse Side