

RECEIVED

WELL NAME & NUMBER Carrasco "14" #3

LOCATION Eddy County, New Mexico
(Give Unit, Section, Township and Range)

OPERATOR R.B. Operating Company 2412 N. Grandview Suite 201 Odessa, TX 79761

DRILLING CONTRACTOR Grace Drilling Company P.O. Box 34180 Odessa, TX 79768

Q. & B.
ARRESTS OFFICE

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above-described well and that he has conducted deviation tests and obtained the following results:

DEGREES @ DEPTH	DEGREES @ DEPTH	DEGREES @ DEPTH	DEGREES @ DEPTH
0.75 - 323	1.25 - 2645		
1.00 - 675	1.00 - 2812		
0.75 - 825	0.50 - 2966		
0.75 - 993	0.50 - 3183		
1.25 - 1147	0.25 - 3630		
3.00 - 1300	1.25 - 4101		
2.25 - 1393	0.75 - 4593		
1.75 - 1516	1.25 - 5085		
1.00 - 1671	1.00 - 5576		
1.25 - 1823	1.25 - 6055		
1.75 - 1978			
2.00 - 2132			
3.00 - 2287			
2.25 - 2379			
1.75 - 2503			

Drilling Contractor Grace Drilling Company

By [Signature]

Subscribed and sworn to before me this 4th day of June, 1990

[Signature]
Notary Public

My Commission Expires 6/30/90

Ector County Texas