

YATES PETROLEUM CORPORATION
Flora AKF State #1
Section 2-T22S-R31E
Eddy County, New Mexico

DRILL STEM TEST RESULTS

DST #1 6761-6785': TIMES: TO 30"; SI 60"; TO 60"; SI 120"; TO 60". RECOVERY:
334' OF OIL, 143' OF WATER. SAMPLER: .14 cfg, 2050 cc oil and 200 cc water.
PRESSURES: IHP 3084; IFP 26-52; ISIP 1451; 2nd FP 52-78; 2nd SIP 2615; 3rd FP
78-130; FHP 3058.

DST #2 6919-7018': TIMES: TO 30"; SI 60"; TO 60"; SI 120"; TO 60". RECOVERY:
751' of oil and 204' of formation water. SAMPLER: .24 cfg, 1700 cc oil and
500 cc water. PRESSURES: IHP 3136; IFP 26-78; ISIP 1169; 2nd FP 104-156; 2nd SIP
2252; 3rd FP 156-235; FHP 3136.

FW 15/94