

11. OTHER INFORMATION:

Topography: Land surface is undulatory and duned with drainage tributary to the Pecos River with marked gullying to the north and south. Slope is 0.95 degrees.

Soil: Detritus of the area consists mainly of coarse clay, silt and sand with some sporadic loose gravels and cobbles.

Flora and Fauna: Vegetation cover primarily consists of creosote bush, broom snakeweed, mesquite, cane flower, fluff grass and ring muhly. Wildlife in the area is that typical of semi-arid desert land and includes coyotes, rabbits, rodents, reptiles and some birds.

Ponds and Streams: The Pecos River runs about 1 mile to the west and 1/2 mile to the south of location.

Residences and other structures: None

Archaeological, Historical and Cultural Sites:

Section 29, T24S, R29E

NMAS 5507 is situated within 4600' of location.

NMAS 5508 is situated within 1400' of location.

NMAS 06-4957 is situated within 3000' of location.

Archaeological Site: (Category 2 Site)

NM-06-4559 located in Section 30, T24S, R29E is situated within 100' of location.

Land Use: Hunting and hunting-related in season.

12. OPERATORS REPRESENTATIVE:

The field representative responsible for assuring compliance with the approved surface-use and operations plan is as follows:

Mr. Dewey Smeltzer
3321 Neely
Midland, Texas 79707

Phones: Business - 1-915/686-3601
Home - 1-915/697-7719