

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
811 S. 1st St.
Artesia, NM 87003-2834

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Gas
☒ Well ☐ Well ☐ Other

2. Name of Operator

STRATA PRODUCTION COMPANY

3. Address and Telephone No.

P. O. Box 1030
Roswell, New Mexico 88202-1030 505-622-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2315' FSL & 1746' FWL
Section 12-23S-29E

5. Lease Designation and Serial No.

NM-0556859-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Nash Unit

8. Well Name and No.

Nash Unit #13

9. API Well No.

30-015-27316

10. Field and Pool, or Exploratory Area

Nash Draw Brushy Canyon Delaware

11. County or Parish, State

Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐


Notice of Intent

☒

Subsequent Report

☐

Final Abandonment Notice



Abandonment

Recompletion

Plugging Back

Casing Repair

Altering Casing

OTHER

☐

Change of Plans

☐

New Construction

☐

Non-Routine Fracturing

☐

Water Shut-Off

☐

Conversion to Injection

☐

Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

04/12/99: MIRU. TOH with rods, pump and tubing. NU BOP.

04/14/99: Perf 15 .42 holes at 6251'-6265'. Acidize with 1500 gallons 7 1/2% acid. Swab test.

04/15/99: Frac with 3000# 16/30 sand. Swab test.

04/16/99: Perf 5 .42 holes at 5677'-5682'. Acidize with 750 gallons 7 1/2% acid. Frac with 3000# 16/30 sand. Swab test.

04/20/99: Perf 10 .42 holes at 5394'-5403'. Acidize with 750 gallons 7 1/2% acid. Frac with 11090# 16/30 sand.

04/22/99: TIH with production string. Flange up wellhead.

04/23/99: TIH with rods and pump. Hang on and start pumping. Well placed on production.

14. I hereby certify that the foregoing is true and correct

Signed Carol J. Garcia

Title Production Records Manager

Date 5/18/99

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: