Feburary 10, 1997

WELL NAME AND NUMBER:

LOCATION: OPERATOR:

HB "11" FEDERAL #3 Sec.11 T24S R29E SANTA FE ENERGY

**DRILLING CONTRACTOR:** 

ZIADRIL, Inc.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and that he has conducted deviation tests and obtained the following results:

DEGREE AND DEPTH		DEGREE AND DEPTH		DEGREE AND DEPTH	
1.00 0.75 1.00 1.25 1.00 0.75 1.34 1.25 1.25 1.50	385' 864' 1365' 1710' 1961' 2213' 2462' 2553' 2678' 2772'	1.50 0.50 0.75 1.25 1.00 1.75 2.00 2.50 2.50 1.75	2940' 3433' 3930' 4430' 4930' 5430' 5914' 6112' 6203' 6296'	1.50 1.75 2.25 1.75 2.25 2.00 1.50 1.00 0.75 0.50	6389' 6587' 6825' 6947' 7167' 7292' 7357' 7481' 7823'
			3200	0.00	8300'

Drilling Contractor: ZIADRIL, Inc.

Billy lenson

Subcribed and sworn to before me this 10th day of December.

My Commission Expires: December 7, 2000

Nancy A.∕Shelley