

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

YATES PETROLEUM CORPORATION

(505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310' FSL & 330' FWL of Section 13-T24S-R29E (Unit 1, NWSW)

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

NM-88136

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Corral Draw AQH Fed #1

9. API Well No.

30-015-29396

10. Field and Pool, or Exploratory Area

Cedar Canyon Delaware

11. County or Parish, State

Pierce Crossing Bone Spring East

Eddy Co., NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Pull RBP & commingle
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-13-97 - Moved in and rigged up pulling unit. TOOH with rods and pump. TIH with tubing and tagged up at 8401'. Shut down for night.
11-14-97 - TIH with tubing to RBP at 8490'. Found 3' of sand on top of RBP. Circulated sand off RBP. Latched onto RBP at 8490'. TOOH with RBP and tubing.
11-15-97 - TIH with pump and rods. Seating nipple set at 8975', tubing anchor at 8910'. Returned to production.

Perfs open: 6005-6832' (Delaware)
8042-9070' (Bone Springs)

DHC Order No.: DHC-1696

Cedar Canyon Delaware Pool - Oil 75%, Gas 100%
Pierce Crossing Bone Spring, East Pool - Oil 25%, Gas 0%

ACCEPTED FOR RECORD

DEC 15 1997

BLM

(ORIG. SGD.) GARY GOURLEY

14. I hereby certify that the foregoing is true and correct

Signed Rusty Klein

Title Operations Technician

Date Nov. 21, 1997

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date _____