| • | | | | ر ۱۶ | , 1 | | |
|--|--|--------------|--------------------------------------|---------------------------|--|---------------|----------|
| Submit 3 Copies To Appropriate District | | | | C\2 | Λ. | | |
| Office District I | State of New Mexico | | | 7 | P() | Form C | :-103 |
| 1625 N. French Dr., Hobbs, NM 87240 | Energy, Minerals and Natural Resources | | | | Rev | ised March 25 | |
| District II | | | | WELL AP | I NO. | | |
| 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION District III | | | | 30-015- 30895 | | | |
| 1000 R to Brazos Rd., Aztec, NM 87410 2040 South Pacheco | | | | 5. Indicate Type of Lease | | | |
| District IV Santa Fe NM 97505 | | | | STATE FEE | | | |
| 2040 South Pacheco. Santa Fe. NM 87505 | | | | 6. State C | il & Gas Lea | se No. | |
| SUNDRY NOTICE | S AND REPORTS C | ON WELL: | S | V- | 4555-2 | | |
| 1 DO NOT USE THIS FURM FUR PROPOSALS TO DRILL OR TO DEFERRE OF THE PROPERTY OF | | | | /. Lease N | ame or Unit A | Agreement Na | ame: |
| PROPOSALS.) FOR SUCH | | | | | , | | |
| 1. Type of Well: | | | | Beretla | r d 24 | i te | |
| Oil Well Gas Well | Other . | | | | | | |
| 2. Name of Operator √ | | | | 8. Well No | | | |
| OXY USA Inc. 16696 | | | | 99 / Y | | | |
| - Tables of Operator | | | | 9. Pool name or Wildcat | | | |
| P.O. BOX 50250 MIDLAND, TX 79710-0250 4. Well Location | | | | Carlsbad Morrow, South | | | |
| Wen Education | | | | Capric Hollow, South | | | |
| Unit Letter K | 180 feet from the | 5. 1 | | | | | |
| | ect non the | _ 20at | $\frac{L}{L}$ line and $\frac{Z}{L}$ | 180_fe | et from the _ | West | line |
| Section 9 | Township 7 | 235 R2 | ange 26E | NACOLA | | | · |
| 10 | Elevation (Show) | whether D | R. RKB. RT GR etc | NMPM | EDDY | Cou | nty |
| | | 2200 | • | * | | | |
| 11. Check Appr | opriate Box to In | dicate Na | ature of Notice. I | Report or O | ther Doto | | |
| DEDECTION OF INTE | NTION TO: | | SUB | SECHENT | REPORT | . 05 | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | | | | C QUENT | | | |
| TEMPORARILY ABANDON C | 141105 51 1115 | | | | | RING CASING | G 📙 |
| COMMENCE DRI | | | | LLING OPNS. | LING OPNS. 🔀 PLUG AND | | |
| PULL OR ALTER CASING MULTIPLE CASING TEST A | | | ABANDONMENT | | DONMENT | | |
| COMPLETION CEMENT JOB | | | | ID | 12 3. | | |
| OTHER: | | | | | | | |
| | (0) | | OTHER: | | | | |
| 12. Describe proposed or completed of of starting any proposed work). SE | FRITE 1102 For | tate all per | tinent details, and g | ive pertinent d | ates, includin | g estimated c | late |
| of starting any proposed work). SE or recompilation. | L ROLL 1103. FOI | Munipie C | completions: Attach | wellbore diag | gram of propo | sed completi | on |
| | | | | | | • | |
| | | | | | 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1 | | |
| | | | | | | | |
| | | | | - | | | |
| | | | | | e e | 7. | |
| See other side | | | | - | | | |
| | | | | | | | |
| | see oth | ven Si | i e | | | | |
| | | | | | 19 | | |
| | | | | | | • | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| I hereby certify that the information above | | | | | | | |
| I hereby certify that the information above | is true and comple | te to the b | est of my knowledge | e and belief. | | | — |
| SIGNATURE_ | | TITLE | DECLII ATODALA | | | _1 . | |
| 7 2224 | | _****** | REGULATORY A | <u>NALYST</u> | DATE | 2/16/00 | <u> </u> |
| Type or print name DAVID | STEWART | | 7 | Celenhona Na | . 915-685-571 | 17 | |
| (This space for State use) | w. Sum | | | | | | _ |
| ADDDD OVED BY |) W. R. | ر | 0.4. | | | | |
| APPPROVED BY | | TITLE | Pistrict. | Sugarvu | OU DATE | 3-2-00 | |
| Conditions of approval, if any: | | | | | | | |

ATTACHMENT C-103 OXY USA INC. BERETTA STATE #1Y SEC 9 T23S R26E EDDY COUNTY, NM

NOTIFIED NMOCD 12/31/99, MIRU FWA-PETERSON #301, SPUD WELL @ 0115hrs MST 12/31/99. DRILL 17-1/2" HOLE, LOST RETURNS @ 379'. M&P LCM PILL W/ NO RESULTS. DRILL TO TD @ 650'W/ NO RETURNS, 1/1/00. RIH W/ 13-3/8" 48# H40 CSG & SET @ 650'. M&P 200sx CL H W/ 10% A-10B + 10#/sx GILSONITE + .25#/sx CELLO-FLAKE + 1% CaCl2 FOLLOWED BY 350sx 35:65 POZ/C W/ 6% BENTONITE + 2% CaCl2 + 5#/sx GILSONITE + .25#/sx CELLO-FLAKE FOLLOWED BY 200sx CL C W/ 2% CaCl2, DISP W/ FW, PLUG DOWN @ 1/1/00, CEMENT DID NOT CIRCULATE, WOC-6hrs. NMOCD NOTIFIED ABOUT CEMENT JOB & THEN ABOUT CMT NOT CIRCULATING, DID NOT WITNESS CMT JOB. RIH W/ TEMP SVY, TOC @ 277', RIH, M&P 6 - 50sx Cl C CMT W/ 5% CaCl2, WOC. M&P 150sx & 140sx CMT, CIRC 12sx CMT TO PIT. RIH & TAG @ 84', M&P 50sx Cl C CMT W/ 5% CaCl2, WOC. RIH, M&P 3-50sx Cl C CMT W/ 5% CaCl2, CIRC 12sx TO PIT. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 500#, OK. NU BOP & TEST BLIND RAMS & CASING TO 500#, OK. TEST PIPE RAMS & HYDRIL TO 500#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD 1/3/00.

DRILL 12-1/4" HOLE TO TD @ 1950', 1/7/00, CHC. RIH W/ 9-5/8" 36# CSG & SET @ 1950'. M&P 1100sx 35/65 POZ/C W/ 6% BENTONITE + 5#/sx GILSONITE + .25#/sx CELLO-FLAKE FOLLOWED BY 200sx Cl C CMT W/ 2% CaCl2, DISP W/ FW, PLUG DOWN @ 1/8/00. CIRCULATE 260sx CMT TO PIT, WOC. NMOCD NOTIFIED & BUT DID NOT WITNESS. CUT OFF CSG & WELD ON WELLHEAD, TEST TO 1500#, OK. NU BOP & MANIFOLD, RU SAFETY TEST & TEST TO 5000#, OK. TEST CSG TO 2500#, OK. TOTAL WOC- 20hrs. RIH, DO CMT & SHOE, DRILL NEW FORMATION 1/9/00, TEST CSG, OK.