

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-015-32508

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

VA-1691

7. Lease Name or Unit Agreement Name:

Chimay BAO State

8. Well No.

1

9. Pool name or Wildcat

Hess Morrow East

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-104) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street Artesia, NM 88210

4. Well Location

Unit Letter E : 1988 feet from the North line and 155 feet from the West line

Section 2 Township 24S Range 23E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

4502' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Set conductor and surface casing <input checked="" type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1/9/03 - Set 40' of 20" conductor pipe. Notified Van Barton with OCD.

1/11/03 - Resumed drilling at 11:00 AM.

1/12/03 - Ran 9 joints 13-3/8" 48# H-40 casing set at 389'. Texas Pattern guide shoe set at 389'. Float collar set at 346'. Cemented with 200 sx Class "H" with additives. Tailed in with 425 sx Class "C" with additives. Cement did not circulate. Ran 1" as follows: Ran 1". Tagged cement at 235'. Spotted 50 sx Class "C" with additives. WOC 1 hr. Ran 1". Tagged cement at 230'. Spotted 25 sx Class "C" with additives. WOC 1 hr. Ran 1". Tagged cement at 192'. Spotted 25 sx Class "C" with additives. WOC 1 hr. Ran 1". Tagged cement at 192'. Spotted 25 sx Class "C" with additives. WOC 1 hr. Ran 1". Tagged cement at 169'. Spotted 50 sx Class "C" with additives. WOC 3-1/2 hrs. Ran 1". Tagged cement at 99'. Spotted 100 sx Class "C" with additives. Circulated 10 sx to pit. WOC 24 hrs. Reduced hole to 7-7/8" and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tina Huerta TITLE Regulatory Compliance Supervisor DATE January 15, 2003

Type or print name Tina Huerta

Telephone No. 505-748-1471

(This space for State use)

APPROVED BY

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

DATE

JAN 24 2003

Conditions of approval, if any: