



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. LC 068335

Unit RECEIVED

JAN 12 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 24, 1960

Federal

Well No. 1 is located 660 ft. from ~~ANY~~ [S] line and 660 ft. from ~~ANY~~ [W] line of sec. 9SW/4 SW/4 Unit M Sec. 9 26-S 31-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Wildcat
(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3230 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-6-60 Pumped 30 sacks of cement across Delaware formation from 4150 to 3982 feet. Pumped 25 sacks across Rustler formation from 1070 to 950 feet. Remainder of hole was filled with low water loss mud.

Subsequent report will be filed when Rotary rig is moved off, marker placed in top of surface casing and location restored to original level.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George L. Buckles Company

Address P.O. Box 56

Monahans, Texas

By /s/ Robert M. Orr

Title Chief Engineer