

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division

Sundry Notices and Reports on Wells

<p>1. Type of Well GAS</p> <hr/> <p>2. Name of Operator <b>BURLINGTON</b> RESOURCES OIL &amp; GAS COMPANY LP</p> <hr/> <p>3. Address &amp; Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700</p> <hr/> <p>4. Location of Well, Footage, Sec., T, R, M 1650' FSL, 1650' FEL, Sec. 28, T-29-N, R-11-W, NMPM, San Juan County</p>	<p>API # (assigned by OCD) 30-045-07810</p> <p>5. Lease Number Fee</p> <p>6. State Oil&amp;Gas Lease #</p> <p>7. Lease Name/Unit Name Mangum</p> <p>8. Well No. 3</p> <p>9. Pool Name or Wildcat Fulcher Kutz Pict Cliffs</p> <p>10. Elevation:</p>
---	---

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other - Bradenhead

13. Describe Proposed or Completed Operations

The bradenhead for the subject well has no bradenhead valve but cement is all the way to surface. The latest bradenhead test report is attached.

(Verbal approval to leave well as is from Charlie Perrin)



CTP 0223251582

SIGNATURE Nancy Oltnans Senior Staff Specialist March 10, 2004

no  
(This space for State Use)

Approved by Charlie Perrin Title DEPUTY OIL & GAS INSPECTOR, DIST. 3 Date MAR 29 2004

**OIL CONSERVATION DIVISION**

API # 30-045-07810

1000 Rio Brazos Road  
Aztec, New Mexico

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 07/24/2002 Operator Burlington Resources Oil & Gas

Lease Name MANGUM Well No 3 Location: U J Sec. 28 Twp. 029N Rge. 011W

Pressure ( Flowing ) Dwt Tubing 21 Intermediate        Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:		BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
	INTERMEDIATE	CASING		
5 Min.	<u>                    </u>	<u>48</u>	Steady Flow <u>                    </u>	<u>                    </u>
10 Min.	<u>                    </u>	<u>                    </u>	Surges <u>                    </u>	<u>                    </u>
15 Min.	<u>                    </u>	<u>                    </u>	Down to Nothing <u>                    </u>	<u>                    </u>
20 Min.	<u>                    </u>	<u>                    </u>	Nothing <u>                    </u> X	<u>                    </u>
25 Min.	<u>                    </u>	<u>                    </u>	Gas <u>                    </u>	<u>                    </u>
30 Min.	<u>                    </u>	<u>                    </u>	Gas & Water <u>                    </u>	<u>                    </u>
			Water <u>                    </u>	<u>                    </u>


If Bradenhead flowed water, check description below:

Clear                                       
Fresh                                       
Salty                                       
Sulfur                                       
Black                                     

Remarks:                                       
Ending: BH Press.: 0 Interm. Press. 0  
Dug down for bradenhead. No bradenhead  
found.  
    
  

By GRACIA MONTOYA 390  
Lease Operator  
    
Position

Witness   



DPNO: 4622901