


District I
P.O. Box 1980, Hobbs, NM
District II
P.O. Drawer DD, Artesia, NM 88211
District III
1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088



SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

PIT REMEDIATION AND CLOSURE REPORT

30-039-07675

Operator: ConocoPhillips (Phillips Petroleum) Telephone: (505) 599-3400

Address: 5525 Highway 64 NBU 3004 Farmington, NM 87401

Facility Or: San Juan 29-6 # 19

Well Name

Location: Unit or Qtr/Qtr Sec B Sec 8 T 29N R 6W County Rio Arriba

Pit Type: Separator _____ Dehydrator _____ Other Abandoned pit

Land Type: BLM _____, State _____, Fee _____, Other: BLM mineral, Private surface

Pit Location: Pit dimensions: Length 15 ft, width 15 ft, depth 3 ft

(Attach diagram)

Reference: wellhead X other _____

Footage from reference: 50 ft

Direction from reference: 10 Degrees _____ East North X
of
X West South _____

Depth to Ground Water: >100 feet
(vertical distance from
contaminants to seasonal
highwater elevation of
ground water)

_____	Less than 50 feet	(20 points)	
_____	50 ft to 99 feet	(10 points)	
<u>X</u>	Greater than 100 feet	(0 points)	<u>0</u>

Wellhead Protection Area:
(less than 200 feet from a private
domestic water source, or: less than
1000 feet from all other water sources).

_____	Yes	(20 points)	
<u>X</u>	No	(0 points)	<u>0</u>

Distance to Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches.)

_____	Less than 200 feet	(20 points)	
_____	200 feet to 1000 feet	(10 points)	
<u>X</u>	Greater than 1000 feet	(0 points)	<u>0</u>

P:\pits\PrC@WK3

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: 1/22/2003 Date Completed: 1/22/03

Excavation X Approx. cubic yards 0

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Method: Onsite N/A Offsite _____

(Check all appropriate sections)

General Description of Remedial Action : A soil sample was obtained from the center bottom of the pit at a depth of 6 feet utilizing U.S.E.P.A. protocol and evaluated for GRO/DRO analysis. The sample was tested and provided oncentrations below NMOCD guidelines.

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit: Sample location Center Bottom

Closure Sampling:
(if multiple samples,
attach sample results

and diagram of sample
locations and depths)

Sample depth 6 feet

Sample date 1/22/03

Sample time 12:04

Sample Results

Benzene(ppm) _____

Total BTEX (PPM) _____

Field Headspace (ppm) non-detect

TPH <10 ppm

Ground Water Sample: Yes _____ No X (if yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETED TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE 10 Feb 03 PRINTED NAME Frank McDonald

SIGNATURE [Signature] and TITLE Environmental Specialist

Client: Conoco Phillips

Project: TPH

Sample ID: 29-6 #19 MV

Lab ID: 0303W00241

Matrix: Soil

Condition: Intact

Date Reported: 01/31/03


Date Sampled: 01/22/03

Date Received: 01/22/03

Date Analyzed: 01/28/03

Parameter	Analytical Result	PQL	MCL	Units
TPH - Method 8015M				
Gasoline Range Organics(C6-C10)	<10	10		mg/Kg
Diesel Range Organics (C10 - C22)	<10	10		mg/Kg
Total Petroleum Hydrocarbons (C6-C22)	<10	10		mg/Kg
Quality Control - Surrogate Recovery				
	%		QC Limits	
4-Bromofluorobenzene(SUR-8015B)	60		50 - 150	
o-Terphenyl(SUR-8015)	113		50 - 150	

Reference: Method 8015AZ, C10 - C32 Hydrocarbons in Soil, Arizona Department of Health Services, Revision - 1.0, 09/25/98.


Reviewed By: 

Location: SJ 29-6 # 19	
Unit Letter: <u>B</u>	Sec. <u>8</u> Twn. <u>29</u> Rng <u>6</u>
Pit Reference from Wellhead:	
50' north 10 degrees W	
Pit:	abandoned
Initial size:	15' x 15' x 3' deep
Final Size:	15' x 15' x 3' deep
Total Cubic Yards:	0
Distances from (ft):	
Groundwater:	>100ft
Wellhead Protection Area:	>1000ft
Nearest Surface Water:	>1000ft
Distance to ephemeral stream:	N/A
Ranking Score (points):	0

Sample ID	Sample Depth (ft)	OVM Reading
1	center @ 6ft	NON DETECT
2		
3		
4		
5		
6		
7		
8		
9		
10		

Comments:
 Topography is mesa top. Soil is brown clay loam.
 No hydrocarbon staining or odor was noticed. Sample was
 extracted from 6 ft below surface (3 ft below pit bottom).
 Sample from 6-ft was sent to IML for GRO/DRO analysis.

Site Diagram:



*drawing not to scale

