

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-045-31402	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. E-503-12	
7. Lease Name or Unit Agreement Name: San Juan 32-7 Unit 31329	
8. Well No. SJ 32-7 Unit #215A	
9. Pool name or Wildcat Basin Fruitland Coal 72629	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6519' GL	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator ConocoPhillips Company 217817	
3. Address of Operator 5525 Highway 64, NBU 3004, Farmington, NM 87401	
4. Well Location Unit Letter F : 2358 feet from the North line and 1990 feet from the West line Section 32 Township 32N Range 7W NMPM County San Juan	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6519' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: Spud Report ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/28/03 MIRU Key #49. Spud 12-1/4" hole @ 2030 hrs 3/28/03. Drilled ahead to 240'. Circ. hole. RIH w/9-5/8", 36#. J-55 casing and set @ 232'. RU Schlumberger to cement. Pumped a preflush of 5 bbls FW, 15 bbls fw & 10 bbls FW w/dye. Pumped 170 sx (181.9 cf - 32.4 bbl slurry) 50/50/G/POZ cement w/9% BWOW D044, 1/4#/sx D029, 0.1 GPS D047 & 0.2% BWPB D045. Dropped wiper plug & displaced w/14.8 bbls FW. Bumped plug w/618 psi @ 0948 hrs 3/29/03. Circ. 63 sx good cement to surface. WOC. NU WH & BOP. PT casing. BOP, rams, and choke manifold to 820 psi w/FW for 30 minutes. Good test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Clugston TITLE SHEAR Administrative Assistant DATE 3/31/03

Type or print name Patsy Clugston Telephone No. 505-599-3454

(This space for State use)

APPROVED BY Chad R. H. TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #1 DATE APR - 3 2003

Conditions of approval, if any: