

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test April 28 Operator Parawon Operating API # 30-0 45-09655

Property Name NE Hogback Unit Well # 37 Location: Unit P Sec N Twn 30 Rge 16

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection ☒ _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): N TA Expires: _____

Casing Pres. 310 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. 260
Int. Casing Pres. _____


Pressured annulus up to * psi. for _____ mins. Test passed/failed

REMARKS: * Casing & Tubing appear to be communicating. Could not bleed down casing to perform test - Operator shut in well.

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)



Revised 02-11-02