

# L & B Speed Drill, LLC

501 Airport Drive · FARMINGTON, NEW MEXICO 87401 · (505)564-3111

Date: March 16, 2004

30-045-32012

To: Manana Gas, Inc.  
C/O Walsh Engineering  
7415 E. Main St.  
Farmington, NM 87401

Re: Directional Survey



Below is the directional survey for your well Crooked Seams  
716' FSL & 1225' EWL, Sec. 14-T30N-R12W

## Degree and Depth

1.0°	131'
.75°	560'
.75°	1310'
1.0°	2012'

## Acknowledgment

State of New Mexico ]

County of San Juan ]

Signed & Acknowledged By: John Durham  
John Durham, Manager

The foregoing instrument was acknowledged before me this 2 day of  
June, 2004

Carrie L. Claassen  
Notary Public

My Commission expires: June 21 2005



