Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No. NMNM048569		
6 If Indian Allottee or	distant Name	

abandoned well. Use form 3160-3 (APD) for such proposals.					o. If fidiall, Allottee of Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. NMNM73738				
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Otl	her					8. Well Name and No. MEXICO FED K 1			
2. Name of Operator Contact: KEN JACKSI FOUR STAR OIL GAS COMPANY E-Mail: kewj@				aco.com		9. API Well No. 30-045-07569-00-S1			
3a. Address 3b. Phone No		. (include a			10. Field and Pool, or Exploratory				
11111 S WILCREST HOUSTON, NM 77099 Ph: 281.5		Fx: 281.561				BASIN DAKOTA	4		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State				
Sec 9 T28N R10W SWSW 1055FSL 0790FWL 36.67227 N Lat, 107.90668 W Lon						SAN JUAN COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATUR	E OF N	OTICE, RI	EPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION								
☐ Notice of Intent	☐ Acidize	□ Dee	Deepen		☐ Production (Start/Resume)		☐ Water Shut-Off		
_	Alter Casing Fracture Treat			☐ Reclamation ☐ Well		☐ Well Integrity			
Subsequent Report	☐ Casing Repair		Construct	_			☐ Other		
☐ Final Abandonment Notice	☐ Change Plans		and Aban	don	☐ Temporarily Abandon				
	Convert to Injection	□ Plug	Back		□ Water I	Disposal			
Four Star Oil & Gas has comp 4/24/2004 MIRU Workover un with 2 3/8" tubing. 4/25/2004 Rig day off 4/26/2004 No pressure on we stopped at 2590' Pull up BP s 6265' Circulated out very hear plug from 6213'-6113'. Pulled Laydown 6 JTS and pull 5STE	iit. No pressure on well the little of the l	is am. Bled of IH with 4-1/2" th 3-7/8" bit a 4-1/2" CIBP a 55416'. Spot	CIBP on nd drilled and set at 12 sks pli	2-3/8" tu out CIB 6263'. S ug from	ubing and P. Push to	ement S O	JUN 2004 89		
14. I hereby certify that the foregoing is		404000		NA 107 - 11 1		2000	0/ 8/ 1/ 9/ 5/5/		
^	For FOUR STAR	OIL GAS COM	PANY, se	nt to the	Farmingto	n	06,116,000		
Name (Printed/Typed) KEN JAC	mmitted to AFMSS for pro KSON	cessing by ST		ON ON US OPLICA	•	4SXM1633SE)			
Tumou Typour Tierro, (O)									
Signature (Electronic S	Submission)		Date 0	6/02/20	04				
	THIS SPACE FO	OR FEDERA	L OR ST	ATE O	FFICE U	SE			
Approved By ACCEPT	ED			PHEN I ROLEU	MASON M ENGINE	EER	Date 06/02/2004		
Conditions of approval, if any, are attache ertify that the applicant holds legal or equivalent would entitle the applicant to conditions.	uitable title to those rights in th uct operations thereon.	e subject lease	Office F						
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations a	a crime for any person to any matter w	erson knowi ithin its juri	ngly and s sdiction.	willfully to m	ake to any department or	agency of the United		

Additional data for EC transaction #31388 that would not fit on the form

32. Additional remarks, continued

4/27/2004 RIH and tag CMT at 5200'. Circulate hole with clean water as per BLM man Mike Wade. POOH and laydown 60 JTS. Rig up Schlumberger and perf 2 holes @ 3482'. RIH CMT retainer and set at 3452'. Sting into retainer and pressure up to 3600 PSI and would not break down. Sting out and spot 12sks above? Pull up to 1880' and spotted 35sks from 1888' to 1500'. POOH and perf two holes at 901'. RIH and set cmt retainer @ 833'. Pump into 2BPM at 1200PSI. Mix and pump 98sks below retainer and spotted 24 sks above. Pull out of hole and perf two holes at 355'. Pump into casing and circulate out bradenhead.

Perf 2880' CR-2837
Mix 16 Lbls coment cap
retainer with 2dbls
per inspectols plugging
report.

4/28/2004 Pump 30 bbls water down casing and circulate out bradenhead. Mix and pump 170 sks 15.6 PPG Class C CMT @ 1.18 CUFT/SK and circulated 7 bbls good cmt to pit. Shut-In and fluid stayed at surface. Cut off wellhead below ground level and installed dry hole marker. RDMO

BLM Reps on location: Mike Wade and Cliff Ollem