

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

High Plains Petroleum Corporation

3. Address and Telephone No.

3860 Carlock Dr., Boulder, CO 80305

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 1980' FEL Sec. 16, T20N, R3W, NMPM

5. Lease Designation and Serial No.

NMNM105185

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

San Isidro #16-10

9. API Well No.

30-043-20719

10. Field and Pool, or Exploratory Area

Rio Puerco Mancos

11. County or Parish, State

Sandoval County,
New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Removal of stored equipment
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6/16/2004 Loaded and removed the concrete pumping unit base, separator and engine.

6/18/2004 Dismantled the pumping unit and removed the stairway for Shogoil's 400 Bbl. tank, which was stored elsewhere.

6/21/2004 Finished dismantling the pumping unit, load and removed the pumping unit, weights, belt guard and concrete sills for the separator, leaving no Shogoil equipment on location. Shogoil's single tank landing was also removed.

ACCEPTED FOR RECORD
JUL 12 2004

14. I hereby certify that the foregoing is true and correct

Signed John B. Somers II Title Petroleum Engineer & Pres. Date June 23, 2004

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any: