SUNDRY Do not use th	UNITED STATES DEPARTMENT OF THE BUREAU OF LAND MAN NOTICES AND REI DIS form for proposals ( Bell. Use Form 3160-3 (	INTERIOR AGEMENT PORTS ON WE	enter an Og	OM B Experes	APPROVED No. 1004-0137 : March 31, 2007 INM 28752 se or Tribe Name	
SUBMIT IN TR	IPLICATE- Other inst	ructions on reve	rse side:		greement, Name and/or No.	-
1. Type of Well Oil Well  2. Name of Operator Resour	Gas Well Other	t Technolo	Chronill gies. LLC		No. w Fed. #1	
3e Address P.O. BOX 1020 4. Location of Well (Footoge, Sec.)	80465  Morrison, CO T.R.M. or Survey Description)  O'FEL, Section	3b. Phone No. (inches) (303) 674	e area code) -6571	Dufers F	or Exploratory Area Ooint Gallup	
12. CHECK A	PPROPRIATE BOX(ES) TO			EPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION  Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize  Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	PE OF ACTION  Production (Statement of the Complete of the Com		Water Shut-Off Well Integrity Other	
Attach the Bond under which ( following completion of the in	ectionally or recomplete horizonta the work will be performed or pro- volved operations. If the operation inal Abandonment Notices shall be	lly, give subsurface locati vide the Bond No. on file a results in a multiple com	ons and measured and tru with BLM/BIA. Require pletion or recompletion i	e vertical depths of all ed subsequent reports : n a new interval, a For	l pertinent markers and zone shall be filed within 30 days nn 3160-4 shall be filed once	<b>5.</b>
Subsequent R From 7/12 t	eport: o 7/17/2004:	RDT Teste	d Casing a	bove 2895	TH w/ Test I 5' @ 1000 PS 3:895' @ 0.5 w/ Test Pa	3I/10 M
On 1/15/200	ermined that 2 Merrion Oil a casin leak a	the Casing & Gas (pr	Leak is b evious Ope	etween 38 rator) ha	395' & <b>4</b> 258' ad determine	ed that

stuck in this hole @ 3967'. to 1000 psi for 10 Min. OK. The casing tested from 4258' to 5500

RDT has MO PU Pending Sundry Notice & Partner AFE Approval.

See Attached Plan for Casing Repair and Current Wellbore Diagram 14. Thereby certify that the foregoing is true and correct Name (Printed/Typed)

Robert A. Schwering, Schwerin Title Operations Manager Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE AUG 0 6 2004 Original Signed: Stephen Mason Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title IB U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Addendum To BLM Sundry Notice Form 3160-5: Scarecrow Federal #1 Well: 7/29/2004:

## Notice of Intent:

RDT plans to circulate an AFE to Repair the Casing in this well. Operations planned are:

- 1. MIRU PU. ND tubinghead. NU BOPE. POOH w/ tubing.
- 2. RIH & Jar Loose or Mill-Over & recover packer body stuck @ 3967'.
- 3. Recover Lower Mandril Body & RBP Retrieving Head.
- 4. Clean-Out well to RBP @ 5500' & dump 2 sx. Sand on RBP.
- 5. Use Squeeze Packer to locate & isolate leak(s) between 3895' & 4258'.
- 6. Squeeze cement casing leak(s) with minimum 50 sx. Cement.
- 7. Drill-out & test casing to minimum 1000 psi. f/ 10 Min.
- 8. Circ. clean & recover RBP.
- 9. RIH w/ Tubing & Clean-Out well if necessary.
- 10. Swab test well to determine productivity.
- 11. Stimulate well if necessary to restore productivity.
- 12. Land tubing for pumping well. ND BOPE. NU tubinghead.
- 13. Run pump & rods & resume oil production.

## **Existing Perforations:**

Upper Gallup Fm.: 5542' – 5674'.

Lower Gallup Fm.: 5702' – 5764'.

Graneros (Upper Dakota) Fm.: 6521' – 6558'.

If the planned fishing operation and casing repair operations are NOT successful then the BLM & NMOCD will be notified of such failure. At that time RDT will inform the BLM & NMOCD of the condition of the wellbore. RDT will then request verbal approval to proceed to abandon the wellbore as contemplated in the Merrion Oil & Gas Sundry Notice, a Notice of Intent to Plug & Abandon this well, submitted to the BLM on 1/19/2004 & approved by the BLM on 1/23/2004. RDT will modify this approved procedure to meet the needs and desires of the BLM & NMOCD at that time.

7/29/2004

A diagram of the current wellbore configuration is attached.