



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 8/12/04 Operator Richardson Oper. Co API # 30-045-07864

Property Name NW Cha Cha Well # 43 Location: Unit ___ Sec ___ Twn ___ Rge ___

Land Type:

State ___
Federal ___
Private ___
Indian X

Well Type:


Water Injection X
Salt Water Disposal ___
Gas Injection ___
Producing Oil/Gas ___
Pressure observation ___

Temporarily Abandoned Well (Y/N): ___ TA Expires: ___

Casing Pres. ___ Tbg. SI Pres. ___ Max. Inj. Pres. ___
Bradenhead Pres. 4 Tbg. Inj. Pres. ___
Tubing Pres. ___
Int. Casing Pres. ___

Pressured annulus up to 600 psi. for 30 mins. Test passed/~~failed~~

REMARKS:




By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK


CHART NO. MC MP-1000 8/12/04

METER _____

CHART PUT ON 12:00 P M
TAKEN OFF 12:30 P M

LOCATION Ulu Che Cha

REMARKS API #30-045



PRINTED IN U.S.A.