



518 17th Street, Suite 1600
Denver, Colorado 80202
(303) 292-5636
FAX (303) 292-5382

P.O. Box 338
Ignacio, Colorado 81137
(970) 563-4000
FAX (970) 563-4116

September 2, 2004

State of New Mexico
Oil Conservation Division
Attn: Charlie Perrin
1000 Rio Brazos Road
Aztec, NM 87410

Re: Alexandra Ballard 1
Section 30-T25N-R11W
API 30-045-27123

Mr. Perrin:

This letter is submitted in regards to your letter dated August 27, 2004 and your phone conversation with Mickey O'Hare regarding the temporary abandonment of the above-referenced well. Please note, the well was tested on May 21, 2004. A copy of our field report, along with the contractors (J.C. Well Service) ticket is attached to verify the work.

Should you have any further questions, please feel free to contact Mickey O'Hare or myself at 970/563-4000.
Thank you.


Sincerely,

Maralex Resources, Inc.

Carla S. Shaw

Carla S. Shaw
Production Technician

cc: A.M. O'Hare



MARALEX RESOURCES, INC.

ALEXANDRA BALLARD # 1

CONTRACTOR: J.C. WELL SERVICE

REPORT DATE: 05/21/04 (JRG)

Make up adapter flange and stripping head on tubing head. Rig up to reverse circulate. Run in hole and tag soft fill at 1312'. Pick up and establish circulation. Wash down 2' and tag up hard. Circulate bottoms up. Had cement nodules in returns. Circulate hole clean. Stack tubing out at 1314'. Pick up and pressure test casing. Work on pump. Pressure up on casing and monitor . Pressure held. Bleed off. Secure well and shut down.



J.C. WELL SERVICE, INC.
P.O. BOX 51
FARMINGTON, NM 87499

DAILY JOB TICKET

15332

TO: MARALEY

DATE 5/21/2004

WELL NO. ALEXANDRIA BALLARD #1

LOCATION _____

CIRCULATE CLEAN TO PLUG. UNLOAD PUMP TRUCK & PIT.
PRESSURE TEST 850 PSI. NEED. SHUT IN. SHUT DOWN.

0700-1730

Rigs & Crew 8.5 hrs. \$1375.00

Hyd. Tongs 85.00

Pump Truck 7 hrs. 350.00

Stripping Head & Flange (RENTAL) 70.00

STEEL PIT 150.00

TRAVEL 2 hrs. 150.00

\$2480.00 2010.00

HOURS: 10.5

Jim Kraver

AUTHORIZED BY