

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 copy to
appropriate
District Office
and 1 copy to
the Santa Fe Office
(Revised 3/9/94)

Rush Outside
VH
BTEX

PIT REMEDIATION AND CLOSURE REPORT

30-039-20786

Operator: Burlington Resources Telephone: 505-326-9841

Address: 3401 East 30th St., Farmington, NM 87402

Facility Or: CANYON LARGO UNIT Well No: 224 Pit No: 1
Well Name

Location: Unit or Qtr/Qtr Sec L Sec 01 T 025N R 006W County Rio Arriba

Pit Type: separator (Separator, Dehydrator, Tank, Vent, Other)

Land Type: BLM (BLM, State, Fee, Other)

Pit Location: Pit Dimension length 10 width 10 depth 3

Reference: wellhead Other _____

Footage from reference: 10

Direction from reference (azimuth): 350 degrees

Depth To Ground Water:

(Vertical distance from
contaminants to seasonal
high water elevation of
ground water.)

Less than 50 feet	(20 points)
50 feet to 99 feet	(10 points)
Greater than 100 feet	(0 points) <u>0</u>

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water
sources.)

RECEIVED
FEB 28 2003
OIL CON. DIV.
DIST. 3

Yes	(20 points)
No	(0 points) <u>0</u>

Distance to Surface Water:

(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches.)

Less than 200 feet	(20 points)
200 feet to 1000 feet	(10 points)
Greater than 1000 feet	(0 points) <u>0</u>

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: 4/4/2002

Date completed: _____

Remediation Method: Excavation _____ Approx. cubic yards: _____
 (Check all appropriate sections.) Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Location: Onsite _____ Offsite _____
 (i.e. landfarmed onsite,
 name and location of
 offsite facility)

General Description of Remedial Action: The lab data from the initial assessment of the pit is detailed below. The pit is NOT located inside the OCD defined Vulnerable Area. Based upon the attached RISK ANALYSIS, it is proposed to close the pit by backfilling with clean soils.

Ground Water Encountered: No (yes or no) Depth: _____

Final Pit:
 Closure Sampling:
 (if multiple samples,
 attach sample results
 and diagram of sample
 locations and depths)

Sample location center of pitSample depth 3Sample Date 4/4/2002Sample time 4:15:00 PM

Sample Results:

Benzene(ppm) 7Total BTEX(ppm) 80Field Headspace(ppm) 805TPH 2100

Ground Water Sample: No (If yes, attach sample results)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Date: 2/26/03Signature Ed HaselyTitle: Environmental SpecialistPrinted Name: Ed Hasely

RISK ANALYSIS FOR EARTHEN PIT CLOSURE

Burlington Resources requests closure of the earthen pit at this location using a limited risk analysis based upon the following conditions:

1. The pit is not located inside the NMOCD defined Vulnerable Areas.
2. Groundwater is estimated to be at a depth greater than 100 feet.
3. The pit is not located within the Wellhead Protection Area - within 200 feet of a private domestic water source or within 1000 feet of all other water sources.
4. The pit is located greater than 1000 feet to surface water.
5. The soils from below the pit bottom were analyzed and the only parameter above NMOCD closure guidelines was total BTEX, which exceeded 50 ppm. The benzene and Total Petroleum Hydrocarbons (TPH) levels were within the NMOCD closure guidelines.

Burlington Resources believes that the earthen pit poses minimal threat to groundwater, human health and the environment.

Client: Burlington Resources
Project: Pit Closure
Sample ID: Canyon Largo UNIT 224 4439801
Lab ID: 0302W01486
Matrix: Soil
Condition: Cool/Intact

Date Reported: 05/30/02
Date Sampled: 04/04/02
Date Received: 04/05/02
Date Extracted: 04/19/02
Date Analyzed: 04/23/02

Parameter	Analytical Result	PQL	Units
BTEX - METHOD 8021B			
Benzene	7	5	mg/Kg
Toluene	16	5	mg/Kg
Ethylbenzene	11	5	mg/Kg
Xylenes (total)	47	15	mg/Kg
Total BTEX	80	30	mg/Kg
GRO/DRO - METHOD 8015M			
Gasoline Range Organics(C6-C10)	2,040	50	mg/Kg
Diesel Range Organics (C10 - C22)	70	50	mg/Kg
Total Petroleum Hydrocarbons (C6-C22)	2,100	100	mg/Kg

Reference: Method 8021b, Volatile Organic Compounds, Test Methods for Evaluating
Solid Waste, Physical/Chemical Methods, United States Environmental
Protection Agency, SW-846, Volume IB.

Reviewed By: 

Analyst: _____