

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-045-25997
5. Indicate Type of Lease STATE ☐ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: BRUCE SULLIVAN
8. Well Number 2
9. OGRID Number 167067
10. Pool name or Wildcat OTERO CHACRA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5736' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other	2. Name of Operator XTO Energy Inc.
3. Address of Operator 2700 Farmington Ave., Bldg. K. Ste 1 Farmington, NM 87401	4. Well Location Unit Letter J : 1700 feet from the SOUTH line and 1480 feet from the EAST line Section 23 Township 28N Range 10W NMPM County SAN JUAN
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5736' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **REPAIR BRADENHEAD** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

XTO Energy Inc. repaired the failed bradenhead by: MIRU. Ppd 10 bbls 2% KCl wtr dwn csg. Ppd 10 bbls 2% KCl wtr dwn TCaA TIH w/tbg. TOH w/tbg, SN & NC. TIH w/csg scraper & tbg. TOH w/tbg & csg scrpr. PU RBP. TIH w/RBP, comp pkr & tbg. Set RBP @ 2700'. Ppd 40 bbls 2% KCl wtr to load well. Set pkr @ 2690'. PT RBP to 600 psig for 5 min. Held OK. Press TCA to 600 psig for 15 min. Held OK. TOH w/tbg & comp pkr. MIRU WL trk. Ran GR/CCL/CBL log fr/2700'-surf w/500 psig on csg. At 9:35 a.m., 8/18/04, notified Sharon @ BLM & ~~BRUCE SULLIVAN~~ @ NMOCD regarding sqz work. MIRU WL trk. Shot 4 sqz holes @ 506' (0.36" hole & 26.36" pene). RDMO WL trk. EIR @ 3.5 BPM & 200 psig dwn csg w/good rtrns out BH vlv. MIRU cmt trk. EIR @ 2.5 BPM dwn csg @ 500 psig w/good rtrns out BH vlv. Ppd 200 scx Class B cmt w/2% CaCl2 (15.6 ppg, 1.18 cuft/sx). Circ 4 bbls cmt our BH vlv. Displ cmt w/3.5 BW. DO soft cmt fr/190'-225'. Do hard cmt fr/225'-424'. Circ hole clean w/2% KCl wtr for 30 min. DO hard cmt fr/424'-516'. Circ csg w/2% KCl wtr for 20 min. PT csg to 500 psig for 30 min; held OK. PT BH to 230 psig. Bled dwn to 140 psig in 10 min. Rlsd press on BH. PT BH to 220 psig; bled dwn to 115 psig in 15 min. Rlsd BH press. Landed tbg @ 2946' & SN @ 2945'. RU swb; 3 runs, 3 hrs, FFL @ 2700' FS & KO flwg. Flwd to pit 1 hr. RWTP @ 1:00 p.m., 8/25/04.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Holly C. Perkins TITLE REGULATORY COMPLIANCE TECH dw DATE 8/31/04

Type or print name HOLLY C. PERKINS Telephone No. 505-324-1090

(This space for State use)

APPROVED BY Chad R. TITLE DEPUTY OIL & GAS DIRECTOR, DIST. #2 DATE AUG 31 2004

Conditions of approval, if any: